

Roofing Material Contains Asbestos Caution Sign

Product Images



Description

Use this **Roofing Material Contains Asbestos Caution Sign** to warn that roofing material contains asbestos.

- Commonly found in laser cutting, laser heat treatment or laser welding facilities.
- Features black wording and border over a bright yellow background.
- Available in a wide range of AS1319 compliant sizes and materials to suit any requirement.
- Caution signs should be placed either in advance of, next to and/or on the relevant hazard.
- Positioning and [sizing](#) of this Caution sign must comply with Australian Standard AS 1319-1994.
- Please note, Australian Standard AS 1319 states that caution sign cannot be used to warn of a hazard that is likely to be life-threatening (we recommend using a danger sign instead).

Additional Information

| | |
|------------------|-----------------|
| Safety Sign Type | Caution |
| Sign Material | Colorbond Steel |
| Sign Size | 450mm x 300mm |