# Crush Zone Caution Sign

## Product Images

## Description

Use this **Crush Zone Caution Sign** to warn staff or visitors to keep clear of a potential crush zone hazard that may pose a risk of injury/harm.

- Commonly found on automatically closing gates or in manufacturing facilities with machines that automatically crush.
- Features black wording, symbol and border over a bright yellow background.
- Available in a wide range of AS1319 in self adhesive vinyl.
- Caution/warning signs should be placed either in advance of, next to and/or on the relevant hazard.
- Positioning and sizing of this Caution sign must comply with Australian Standard AS 1319-1994.
- Please note, Australian Standard AS 1319 states that caution sign cannot be used to warn of a hazard that is likely to be life-threatening (we recommend using a danger sign instead).

| | |
|---|---|
| Safety Sign Type | Caution |

## Additional Information