

Caution S.W.L Caution Sign

Product Images



Description

S.W.L stands for Safe Working Load, meaning the maximum safe force that a piece of equipment can exert without breaking. This **Caution S.W.L Caution Sign** allows a safe working load figure to be written on the line, to convey this important information to staff.

- Commonly found attached to or near a piece of equipment (e.g. a forklift) in a warehouse or facility.
- Features black wording, symbol and border over a bright yellow background.
- Available in a wide range of AS1319 compliant sizes and materials to suit any requirement.
- Caution signs should be placed either in advance of, next to and/or on the relevant hazard.
- Positioning and [sizing](#) of this Caution sign must comply with Australian Standard AS 1319-1994.
- Contact Bronson Safety to have a SWL figure professionally printed, removing the need to write a figure on the line.
- Please note, Australian Standard AS 1319 states that caution signs cannot be used to warn of a hazard that is likely to be life-threatening (Bronson Safety recommends using a danger sign instead).

Additional Information

Safety Sign Type	Caution
------------------	---------

Product Options

Sign Size:	240mm x 180mm
	300mm x 225mm
	600mm x 450mm
Sign Material:	Colorbond Steel
	Polypropylene
	Self Adhesive Vinyl