

Welding Mask Must Be Worn Sign

Product Images



Short Description

Welding Mask Must Be Worn

Description

This mandatory sign indicates a welding mask must be worn. Ideal for warehouses, building and mining sites. Mandatory Signs specify actions that are required to safeguard health and/or avoid injury. Mandatory signs provide specific instructions that must be carried out. These industrial and workplace safety signs are essential for promoting the wearing of PPE and abiding by safe workplace procedures. Symbols (or pictograms) are depicted in white on a blue circular background. Sign wording, if necessary, is in black lettering on a white background.

Additional Information

Safety Sign Type	Mandatory
------------------	-----------

Product Options

Sign Size:	Viewing distance up to 5 metres
------------	---------------------------------

	Viewing distance up to 7 metres
--	---------------------------------

	Viewing distance up to 15 metres
--	----------------------------------

	Viewing distance up to 23 metres
--	----------------------------------

Sign Material:	Indoor or Outdoor use. Lasts 5-8 years.
----------------	---

	Temporary indoor or outdoor use.
--	----------------------------------

	Indoor or Outdoor use. Lasts 3-5 years.
--	---

	Indoor use. Lasts 5-8 years.
--	------------------------------