

Danger Formwork Stripping In Progress Sign

Product Images



Description

The Danger Formwork Stripping In Progress Sign shows the area is a high risk with formwork stripping in

progress where falling materials or objects could occur and cause injury.

Danger signs are safety signs for warning of a particular hazard or hazardous condition that is likely to be life-threatening. Danger safety signage has many uses and can warn of many dangerous situations – such as fuel storage, radiation, high voltage, chemicals, open holes, and worksite hazards. The sign is shown as the word Danger on a red oval over a black rectangle. Text is black on a white background.

Additional Information

Safety Sign Type	Danger
Product Options	
Sign Size:	300mm x 225mm
	600mm x 450mm
Sign Material:	Colorbond Steel
	Flute
	Polypropylene