

## Machine Starts Automatically Caution Sign

**Product Images** 



## **Description**

Use this **Machine Starts Automatically Caution Sign** to warn workers that an automated machine is present, and to use caution when in the surrounding area to eliminate potential hazards.

- Commonly found in manufacturing facilities where hazardous machinery with automated on/off settings are in use.
- Features black wording and border over a bright yellow background.
- Available in a wide range of AS1319 compliant sizes and materials to suit any requirement.
- Caution signs should be placed either in advance of, next to and/or on the relevant hazard.
- Positioning and sizing of this Caution sign must comply with Australian Standard AS 1319-1994.
- Please note, Australian Standard AS 1319 states that caution sign cannot be used to warn of a hazard that is likely to be life-threatening (we recommend using a danger sign instead).

## **Additional Information**

Safety Sign Type	Caution	

## **Product Options**

Sign Size:	240mm x 180mm
	300mm x 225mm
	600mm x 450mm
Sign Material:	Colorbond Steel
	Polypropylene
	Self Adhesive Vinyl

9/5/25